



## **Daily Update**

May 2

### **Geological Work**

Devil's Slide (post mile 39.14)

- Inclinometers are being read every day to monitor slide movement.

### **Repair Work**

Devil's Slide (post mile 39.14)

- The slide area is being prepared for repair work to begin. Old electrical systems installed to detect slide movement are being removed. Guardrails and associated debris are also being taken up.
- On the slope above the road, steel mesh will be lifted and accumulated rocks removed. The mesh will be re-anchored to the slope after the loose rocks are cleared.

Slide at Post Mile 40

- Repair work continued today. Reconstruction of the embankment is due to be complete by the end of the week.